

	Type	L #	Hits	Search Text	DBs	Time Stamp
1	IS&R	L1	1854	((82/124-127) or (414/14,17,736)).CCLS.	US- PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2006/08/16 11:44
2	BRS	L2	22	1 and bar and "bar pusher" and spindle and lathe	US- PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2006/08/16 11:48
3	BRS	L4	15039408	@ad<"19970408"	US- PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2006/08/16 11:47
4	BRS	L3	2	2 and carriage and grip	US- PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2006/08/16 11:47
5	BRS	L5	1	(bar and "bar pusher" and spindle and lathe and carriage and grip).clm.	US- PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2006/08/16 11:49
6	BRS	L6	1	(bar and "bar pusher" and spindle and lathe and carriage).clm.	US- PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2006/08/16 11:50

7	BRS	L7	3	(bar and "bar pusher" and spindle and lathe).clm.	US- PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2006/08/16 11:49
---	-----	----	---	---	--	---------------------

	Type	L #	Hits	Search Text	DBs	Time Stamp
8	BRS	L8	103	(bar and "bar pusher").clm.	US- PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2006/08/16 11:49
9	BRS	L9	1	("bar pusher" and spindle and lathe and carriage).clm.	US- PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2006/08/16 11:50
10	BRS	L10	91	(spindle and lathe and carriage) .clm.	US- PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2006/08/16 11:52
11	BRS	L11	4	(spindle and lathe and carriage and collet).clm.	US- PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2006/08/16 11:52
12	BRS	L12	1	(spindle and lathe and carriage and collet and "bar pusher" and offset).clm.	US- PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2006/08/16 11:59
13	BRS	L13	1	(spindle and lathe and carriage and collet and "bar pusher") .clm.	US- PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2006/08/16 11:59

14	BRS	L14	4	(spindle and lathe and carriage and collet).clm.	US- PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2006/08/16 11:59
----	-----	-----	---	---	--	---------------------

	Type	L #	Hits	Search Text	DBs	Time Stamp
15	BRS	L15	0	(spindle and lathe and carriage and collet and lockable).clm.	US- PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2006/08/16 12:00
16	BRS	L16	2	(spindle and lathe and carriage and collet and guide).clm.	US- PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2006/08/16 12:00
17	BRS	L17	2	(spindle and lathe and carriage and collet and guide and support).clm.	US- PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2006/08/16 12:01
18	BRS	L18	0	(spindle and lathe and carriage and collet and guide and support and load).clm.	US- PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2006/08/16 12:01
19	BRS	L19	1	(spindle and lathe and carriage and collet and guide and support and loading).clm.	US- PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2006/08/16 12:02
20	BRS	L20	0	(spindle and lathe and carriage and collet and guide and support and bar adj loading).clm.	US- PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2006/08/16 12:02